

FR Repairability Index Final Score

Name of the product:	Pixel 7a
Date of completion:	March 1, 2023
Producer's Name	Google LLC
Producer's Address	1600 Amphitheatre Parkway Mountain View, CA 94043 United States

Pixel 7a Final Repairability Score

Icon to be published at check out point and characteristics of the product section



INDICE DE RÉPARABILITÉ

Pixel 7a Scorecard (English)

Criteria	Sub-Criteria	Score of sub criterion /10	Weighting factor of sub criterion	Score of criterion /20	Total criteria scores /100
CRITERION 1 : Documentation	1.1 Availability of the technical documentation and other documentation related to user and maintenance instructions	8.1	2	16.2	80.1
	CRITERION 2 : Disassembly, accessibility, tools and fasteners	2.1 Ease of disassembly parts from List 2*	7.5	1	
	2.2 Necessary tools (List 2)	4.4	0.5		
	2.3 Fasteners characteristics parts from List 1** and List 2	3.5	0.5		
CRITERION 3 : Availability of spare parts	3.1 Availability over time parts from List 2	7.1	1	14.5	
	3.2 Availability over time parts from List 1	7.1	0.5		
	3.3 Delivery time parts from List 2	7.5	0.3		
	3.4 Delivery time parts from List 1	7.5	0.2		
CRITERION 4 : Price of spare parts	4. Ratio between price of parts from list 2 to the price of the product	10	2	20	
CRITERION 5 : Specific criterion	5.1 Accessibility of usage-counter to consumers	10	1	18	
	5.2 Free remote assistance	6	0.5		
	5.3 Possibility to reset softwares	10	0.5		
FR Repairability Index Final Score					8