

FR Repairability Index Final Score

Name of the product:	Pixel 8 Pro
Date of completion:	July 19, 2023
Producer's Name	Google LLC
Producer's Address	1600 Amphitheatre Parkway Mountain View, CA 94043 United States

Pixel 8 Pro Final Repairability Score

Icon to be published at check out point and characteristics of the product section



Pixel 8 Pro Scorecard (English)

Criteria	Sub-Criteria	Score of sub criterion /10	Weighting factor of sub criterion	Score of criterion /20	Total criteria scores /100
CRITERION 1 : Documentation	1.1 Availability of the technical documentation and other documentation related to user and maintenance instructions	8.1	2	16.2	82.4
	CRITERION 2 : Disassembly, accessibility, tools and fasteners	2.1 Ease of disassembly parts from List 2*	7.5	1	
	2.2 Necessary tools (List 2)	5.0	0.5		
	2.3 Fasteners characteristics parts from List 1** and List 2	3.5	0.5		
CRITERION 3 : Availability of spare parts	3.1 Availability over time parts from List 2	7.2	1	14.5	
	3.2 Availability over time parts from List 1	7.1	0.5		
	3.3 Delivery time parts from List 2	7.5	0.3		
	3.4 Delivery time parts from List 1	7.5	0.2		
CRITERION 4 : Price of spare parts	4. Ratio between price of parts from list 2 to the price of the product	10	2	20	
CRITERION 5 : Specific criterion	5.1 Accessibility of usage-counter to consumers	10	1	20	
	5.2 Free remote assistance	10	0.5		
	5.3 Possibility to reset softwares	10	0.5		
FR Repairability Index Final Score					8.2